

TOOL SETTING PROCEDURE

The following procedure should be adhered to :-

- Datum the machine
- Any offsets already in the file can be overwritten.
- Select tool in MDI,(JOG mode).
- Press T, then tool number required, then EOB. The correct tool will now be selected.
- Start the Spindle - Press S, then a spindle speed, then press EOB.
- Press SPINDLE CW.
- Using AXIS JOG keys, touch on the end of the bar.
- Press the MENU\OFFSET Key.
- Press MZ 0 EOB Z now reads zero.
- Press RESET or CANCEL Key.
- Turn an outside diameter and move away in the Z Axis only.
- Stop the Spindle and measure the outside diameter just turned.
- Press MENU OFFSET Key.
- Press MX and input the measured diameter.
- Press RESET or CANCEL Key.
- Return machine to " home " position.
- Repeat the above procedure for the remaining tools.
- To save the OFFSETS press F9,which brings up the offset menu,then select SAVE OFFSETS.