



ALL FUSES
3.15 AMPS

F1 = SPINDLE DRIVE
F2 = CONTROL TRANS
F3 = AXIS DRIVE
TRANS
F4 = 110v CIRCUIT
F5 = SPRAY MIST
(OPTION)


FENNER DRIVE CONNECTIONS




75va TRANSFORMER



MAINS IN



ISOLATOR



24v
POWER
SUPPLY

SHEET No 2

STARMILL PC
RELAY CONNECTIONS

OF

DENFORD MACHINE TOOLS LTD

BRIGHOUSE

WEST YORKSHIRE

DRN BY A McHENRY

DATE 11-01-91

A3- 400202