
NextMove ST
OPTIDRIVE
MOTOR
VACUUM PUMP
MOTOR
SPINDLE MOTOR
OPTIONAL 4TH AXIS
4TH AXIS
PARALLEL WIRED
X AXIS
Y AXIS
Z AXIS
SPEED POT
FSED POT
VACUUM SWITCH
SPINDLE ENABLE
E-STOP CONTROL
VACUUM RELAY
GUARD RELEASE
SPINDLE DISCONNECT
Z BRAKE RELEASE
GUARD SWITCH STATUS
VACUUM BUTTON
E-STOP STAT
SPIN CONNECTED
EARTH
L1 L2 L3
U V W
MAINS INPUT
Z BRAKE
LAMP
FAN
0V
220V
110V
BI00373G
RL1: E-STOP
RL2: SPINDLE ENABLE
RL3: GUARD RELEASE
RL4: VACUUM RELAY
RL5: Z AXIS BRAKE RELEASE
RL6: SPINDLE DISCONNECT
D: CROSS MONITORED GD & ESTOP
Drawn S. ODDY
Check S. ODDY
Project COMPACT 1000 PRO
Title ELECTRICAL SCHEMATIC
Drawing No. MRC003000D
Sheet 1 of 1