

STARMILL SPINDLE DRIVE  
CONNECTIONS

L	N	A+	A-	C	C
---	---	----	----	---	---

1	2	3	4
0v	COM		+15
RED	ORG		BRN

0v	COM		+15	OPTION
RED	YLW		BLE	

SHEET No

OF