

PARAMETER SHEET FOR TRIAC ROCHDALE

N0535 P - - - - - 30
 N0536 P - - - - - 65
 N0537 P - - - - - 40
 N0700 P - - 274000
 N0701 P - - - 19000
 N0702 P - - - 16000
 N0703 P - - - - - 0
 N0704 P - - - 16000
 N0705 P - - - 151000
 N0706 P - - - 187000
 N0707 P - - - - - 0
 N0708 P - - - - - 0

N0900 P 00111001
 N0901 P 01000000
 N0902 P 00000000
 N0903 P 00000000
 N0904 P 00000000
 N0905 P 00000001
 N0906 P 00100001
 N0907 P 01010100
 N0908 P 00001000
 N0909 P 01000000
 N0910 P - - - - -
 N0911 P - - - - -
 N0912 P - - - - -
 N0913 P - - - - -

LIST ANY SPECIAL CHANGES NECESSARY FOR THIS MACHINE BELOW:

N - - - - P - - - -
 N - - - - P - - - -
 N - - - - P - - - -
 N - - - - P - - - -
 N - - - - P - - - -
 N - - - - P - - - -
 N - - - - P - - - -
 N - - - - P - - - -

LIST ANY DIAGNOSTICS SET TO "1"

DGN No	BIT NO's
450	6.
451	6,1,0
452	5
453	3,1
454	1

CTRL S/NO 1122230

PLC NO 3-506

PARAMETER SHEET FOR TRIAC ROCHDALE

N0535 P - - - - - 30
 N0536 P - - - - - 65
 N0537 P - - - - - 40
 N0700 P - - 274000
 N0701 P - - - 19000
 N0702 P - - - 16000
 N0703 P - - - - - 0
 N0704 P - - - 16000
 N0705 P - - - 151000
 N0706 P - - - 187000
 N0707 P - - - - - 0
 N0708 P - - - - - 0

N0900 P 00111001
 N0901 P 01000000
 N0902 P 00000000
 N0903 P 00000000
 N0904 P 00000000
 N0905 P 00000001
 N0906 P 00100001
 N0907 P 01010100
 N0908 P 00001000
 N0909 P 01000000
 N0910 P - - - - -
 N0911 P - - - - -
 N0912 P - - - - -
 N0913 P - - - - -

LIST ANY SPECIAL CHANGES NECESSARY FOR THIS MACHINE BELOW:

N - - - - P - - - -
 N - - - - P - - - -
 N - - - - P - - - -
 N - - - - P - - - -
 N - - - - P - - - -
 N - - - - P - - - -
 N - - - - P - - - -
 N - - - - P - - - -

LIST ANY DIAGNOSTICS SET TO '1'

DGN No	BIT NO'S
450	6.
451	6,1,0
452	5
453	3,1
454	1

CTRL S/NO 1122230

PLC NO 3-506